




Mounting bracket Smoke / CO detector Screws (2) Stickers (2)
Wall anchors (2)
3V Lithium battery

Placement tips

Place on flat surface. See **Placement Diagrams** (pg. 13).

FIGURE 1



Smoke / CO Detector

The ShieldPro Smoke / Carbon Monoxide (CO) detector's alarm sounds when either smoke or CO levels get too high.

Mount your Smoke / CO Detector

STEP 1

Remove the mounting bracket (see Figure 1).

STEP 2

Install the battery (see Fig. 2). Press the Test button on the smoke detector to test the battery (see Fig. 3, page 13).

STEP 3

Pair with the panel.

Settings (\equiv) > Devices > + > Select Smoke / CO > Follow the panel's instructions to pair your Smoke / CO Detector.


STFP 4

Choose a location for your Smoke / CO detector (See **Placement Diagrams**, page 13).

STEP 5

Use the bracket as a guide and determine where to place the screws (see Fig. 4, page 13).

FIGURE 2



STEP 6

Screw the mounting bracket into the ceiling. Use the wall anchors provided as needed.

STFP 7

Use the provided date sticker to record the date installed and place it on the Smoke / CO detector.

STEP 8

Twist Smoke / CO detector onto the mounting bracket to fix it in place.




FIGURE 3

FIGURE 4


Test/Silence button LED indicator


Placement Diagrams




Bedroom
Bedroom
Ground
Floor
Basement
Smoke/CO Detector


Minimum recommended protection







Recommended best and acceptable locations to mount Smoke / CO detectors.



Recommended location to mount Smoke / CO detectors in rooms with angled ceilings.